


TO BE FILLED BY THE INSPECTING  
OFFICER  
( ASSISTANT ENGINEER )

- Name of Officer : BINU M.M
- Name of School : MES INTERNATIONAL SCHOOL,  
PATTAMBI
- Location/with name of Education  
District/Sub District : Pattambi, Ottappalam, Palakkad
- Classification of building and size : 5 Multistoried RCC Buildings (1. Golden Jubilee  
Auditorium Block, 2. Administrative Block, 3. U  
shaped Auditorium Block)
- Period of which the certificate issued : 2023-2024
- Nature of defects if any
  - Foundation and basement : nil
  - Superstructure : nil
  - Doors & windows : nil
  - Wood work wrought  
and put up : nil
  - Roof : nil
  - Flooring : nil
  - Miscellaneous (cracks etc) : nil
- Any major defects noticed which will  
hender the building unsafe in any manner : No Major defects noticed during inspection.
- Whether maintenance works have been  
Done properly : Yes
- Whether the structure is sound on for  
Conducting classes : The structure is sound for conducting classes  
Under normal wind and weather conditions.

Note : 1. The stability of the structure should be examined also with reference to location, altitude,  
intensity of wind, exposure to load etc.  
2. Any additional observations if deemed necessary for the certificate may be furnished  
separately with the certificate.

Certified that the school was inspected by me on 26-06-2023 and found to be fit/unfit to  
conduct classes for the period 2023-24 for the reasons noted above.

Place : Pattambi  
Date : 30-06-2023



Signature:

*(Handwritten Signature)*  
Assistant Engineer  
L.S.G.D. Section  
PATTAMBI MUNICIPALITY