

APPENDIX C

[See Rule 11(3)]

G.O(M.S)NO.411/11LSGD Dated: 14.02.2011

BUILDING PERMIT

PATTAMBI MUNICIPALITY

FileNo.A4/8969(145)2014

Dated 07/10/2016

Ref:- Application dated 05/09/2016 from Sri/Smt. General Secretary, M E S International School, Kozhikkunnu, Pattambi-PO

Permission is granted for the New Construction Survey No. 53/3, 151/1 in Municipality Pattambi, Taluk Pattambi, District Palakkad for institutional Building Purpose, subject to the conditions stated below:

- 1) Permit is valid up to 06/10/2019.
- 2) K.P.B.R-2011 Should strictly be followed.
- 3) The permit issued for the purpose of construction of office building only.
- 4) Permit fee Rs. 4648/- is remitted as per receipt No. 11428100077, Dated 08.10.2014
- 5) Permit, Approved plan & all other details should be exhibited at the site itself visible to the public during the time of the construction of building as per the Circular of Govt. Of Kerala 33150/R.A1/2012/Isgd Dated 25.07.2012

Plinth Area of the building is as follows.

Cellar	: NA
Ground Floor	: 606.00m ²
First Floor	: 606.00m ²
Second Floor	: 606.00m ²
Total	: 1818.00 m ²

Place: Pattambi
Date: 07/10/2016



R. Ratheenath

Secretary

Pattambi Municipality


ASHA BYJU
PRINCIPAL
MES INTERNATIONAL SCHOOL
P.O. Pattambi, Palakkad Dt,
Kerala - 679303, INDIA
CBSE Affin No: 930072 / School No: 75052
pgt.mespts@gmail.com





K.S.B.A. THANGAL
CHAIRMAN
MES INTERNATIONAL SCHOOL
P.O. Pattambi, Palakkad Dt.
Kerala - 679303, India

TO BE FILLED BY THE INSPECTING OFFICER
(ASSISTANT ENGINEER)

1. Name of Officer : Aboobakker V.P
2. Name of School : MES international school, Pattambi
3. Location/with name of Education District/Sub District : Pattambi, Ottappalam, Palakkad
4. Classification of building and size: 5 Multi storied RCC Building(1 Golden jubilee Auditorium block , 2 Administrative Block 3 U-shaped auditorium block 4 Pre primary Montessori section 5 Primary Montessori section)
5. Period of which the certificate issued : 2020-21
6. Nature of defects if any
 - a) Foundation and basement : Nil
 - b) Superstructure : Nil
 - c) Doors & windows : Nil
 - d) Wood work wrought and put up : Nil
 - e) Roof : Nil
 - f) Flooring : Nil
 - g) Miscellaneous (cracks etc) : Nil
7. Any major defects noticed which will Render the building unsafe in any manner: No Major defects noticed during inspection
8. Whether maintenance works have been Done properly : Yes
9. Whether the structure is sound on for Conducting classes : The Structure is sound for conducting classes under normal wind and weather condition.


Note : 1. The stability of the structure should be examined also with reference to location, Attitude, intensity of wind, exposure to flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished Separately with the certificate.

Certified that the school was inspected by me on 26/05/2020 and found to be fit/unfit to conduct classes for the period 2020-21 for the reasons noted above.

Signature: 

Place : Pattambi

45/05/2020


ASHA BYJU
PRINCIPAL
MES INTERNATIONAL SCHOOL


P.O: Pattambi, Palakkad Dt,
Kerala - 679303, INDIA
CBSE Affin.No: 930072 / School No: 75052
pgt.mespts@gmail.com




K.S.B.A. THANGAL
CHAIRMAN
MES INTERNATIONAL SCHOOL
P.O. Pattambi, Palakkad Dt.
Kerala - 679303, India

Assistant Engineer
Full Additional Charge
LSGD Engineering Section
Pattambi Municipality